

MT410 2.0 Motor Fitment Chart

Type	Diameter	Length	Fitment	Notes
1/10 SC	36mm	52-68mm	Y	
1/10 SC	36mm	68-76mm	Y	portion of esc tray may need to be modified.removed, possiby limits esc size
1/8th buggy	42mm	66-70mm	Y	Minimum 14 tooth pinion to prevent diff output hitting motor, possiby limits esc size
1/8th truggy	42mm	70-80mm	Y	Minimum 14 tooth pinion to prevent diff output hitting motor, portion of esc tray may need to be modified.removed, possiby limits esc size